



FIRE RESISTANT TIMBER FIRE DOORS

Certificate number: IFCC 1358

Certificate only valid if verified on website – www.ifccertification.com

Issued by IFC Certification Ltd, part of the Kiwa UK Group

This is to certify that

TSIGAS SA

Mouzaki, Karditsa, 43060 Greece

Tel: +30 2445043330

Who fabricate the following timber fire doors and or doorsets:

Halspan FD30, FD60, FD90, FD120. Strebord FD30, FD60.

have satisfied the requirements of the SDP 01 Timber Fire Door scheme. This includes the testing of products to BS476: Part 22, the inspection of their Factory Production Control continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes** integrity are detailed on page 2 of this certificate.

> Initial Certification: 17 January 2018 Re-issued: 23 February 2024 Valid to: 16 January 2028 Issue number: 3

David Mowatt Head of Certification - IFC Certification / KIWA Group Limited

This certificate consists of 2 pages. Publication of this certificate is permitted.

IFC Certification Ltd

Ground Floor, Suite A, Building 2 Bear Brook Office Park Walton Street

Avleshury

Buckinghamshire

HP21 7GQ

United Kinadom

T +44 (0)1844 276920











The production of fire-resistant timber doorsets are manufactured in accordance with assessment/ test reports referenced within the following table:

Doorset Description	Fire Rating	Assessment/Test Report
Halspan Prima	FD30	IFCA/06166 (HS01)
Halspan Prima	FD60	IFCA/06167 (HS02)
Halspan Optima	FD30	PAR/10341/01 (HS03)
Halspan Optima	FD60	PAR/10341/02 (HS04)
Halspan	FD90	PAR/10513/01 (HS05)
Halspan	FD120	PAR/10513/02 (HS06)
Strebord	FD30	IFCA/08037 (SS01)
Strebord	FD60	IFCA/08038 (SS02)

Signed on behalf of Kiwa UK



David Mowatt
Head of Certification – IFC Certification /
KIWA Group Limited

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.

IFC Certification Ltd

Ground Floor, Suite A, Building 2
Bear Brook Office Park

Walton Street

Aylesbury

Buckinghamshire

HP21 7GQ

United Kingdom

T +44 (0)1844 276920 www.ifccertification.com

IFC ©©©

