



FIRE RESISTANT TIMBER DOOR SCHEME

Certificate number: IFCC 1358

Certificate only valid if verified on website - www.ifccertification.com

This is a product certificate to certify that

TSIGAS SA

Mouzaki,
Karditsa, 43060
Greece

Tel: 2445043330

Who fabricate the following timber fire doors and or doorsets:

**Halspan FD30, Halspan FD60, Halspan FD90,
Halspan FD120**

Strebord FD30, Strebord FD60, Warmsprings FD90

have satisfied the requirements of the SDP01 Fire resistant Timber Door scheme. This includes the testing of products to **BS476: Part 22**, the inspection of Factory Production Control and continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve from **30 minutes to 120 minutes integrity** are detailed in the schedules referenced below.

Schedule refs: HS01, HS02, HS03, HS04, HS05, HS06, SS01, SS02, WSS02



Initial certification: 17 Jan 2018

Reissued: 22 February 2023

Valid to: 16 Jan 2024

Issue status: 2

Ian Woodhouse

Head Of Technical - IFC Certification



175

IFC Certification Ltd, Ground Floor, Building 2, Bear Brook Office Park, Walton Street, Aylesbury, HP21 7GQ, UK
Tel: +44 (0)1844 276920 E-mail: uk.info@kiwa.com Web: www.ifccertification.com
Registered No: 4777898 England

The certificate and schedule are held in force by regular annual surveillance visits by IFC Certification and the reader or user should contact IFC Certification to validate its status. This certificate remains the property of IFC Certification and must be returned to them on demand.